



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	187	Date:	10/7/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5910		Simmonds	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 53

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0053.JPG

Image Status: Image found and displayed.



Photo No: 54

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0054.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 187

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\187.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	187	Date:	10/7/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5908		Simmonds	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 55

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0055.JPG

Image Status: Image found and displayed.



Photo No: 56

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0056.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 187

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\187.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	187	Date:	10/7/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5906		Simmonds	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	50		

Comments:

SMOKE TEST PHOTOS



Photo No: 57

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0057.JPG

Image Status: Image found and displayed.



Photo No: 58

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0058.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 187

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\187.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	187	Date:	10/7/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	8	Setup No:	7	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5902		Simmonds	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	50		

Comments:

SMOKE TEST PHOTOS



Photo No: 59

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0059.JPG

Image Status: Image found and displayed.




Photo No: 60

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0060.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 187

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\187.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	187	Date:	10/7/2004	MeterBasin:	01_WR04
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	9	Setup No:	7	Priority CCTV:	

House Number	5902	Street Prefix:		Street Name:	Simmonds	Street Type:	AVE
Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:	2=Trace		
Sector:	2=Private	Drainage Area:	50				
Comments:							

SMOKE TEST PHOTOS



Photo No: 59

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0059.JPG

Image Status: Image found and displayed.




Photo No: 60

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0060.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 187

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\187.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5925		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 55

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0055.JPG

Image Status: Image found and displayed.



Photo No: 56

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0056.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5929		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 57

Filename Path:
X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0057.JPG

Image Status: Image found and displayed.




Photo No: 58

Filename Path:
X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0058.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5919		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 59

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0059.JPG

Image Status: Image found and displayed.



Photo No: 60

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0060.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH





SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5917		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS




Photo No: 61

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0061.JPG

Image Status: Image found and displayed.



Photo No: 62

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0062.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5915		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 63

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0063.JPG

Image Status: Image found and displayed.




Photo No: 64

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0064.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5907		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	75		

Comments: Hole at cleanout stack

SMOKE TEST PHOTOS



Photo No: 65

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0065.JPG

Image Status: Image found and displayed.



Photo No: 66

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0066.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5905		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 67

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0067.JPG

Image Status: Image found and displayed.



Photo No: 68

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0068.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	8	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5905		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	100		

Comments: Hole at cleanout stack

SMOKE TEST PHOTOS



Photo No: 69

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0069.JPG

Image Status: Image found and displayed.




Photo No: 70

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0070.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	9	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
5903		Bland	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	3=Moderate
Sector:	2=Private	Drainage Area:	25		

Comments:

SMOKE TEST PHOTOS



Photo No: 71

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0071.JPG

Image Status: Image found and displayed.



Photo No: 72

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_A\A_2004_1007Image0072.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	188	Date:	10/7/2004	MeterBasin:	01_WR05
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	8	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
3107		Parkington	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:	4=Major
Sector:	2=Private	Drainage Area:	0		

Comments:

SMOKE TEST PHOTOS



Photo No: 61

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0061.JPG

Image Status: Image found and displayed.



Photo No: 62

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1007-2004\T-1\PLAYER_B\B_2004_1007Image0062.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 188

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\188.tif

Image Status: Image found and displayed.